



# 2007 Falcon 900EX EASy



## Plane Info

Year and Model	2007 Falcon 900EX EASy	Airframe TT	4,940.4 SNEW
SN	900EX-179	Engine TT	4,940.4 / 4,940.4 / 4,957.7 SNEW
Reg	N718MM	Location	California, USA

## Specs

Airframe	<p>2007 Airframe</p> <p>Total Hours: 4,940.4</p> <p>Total Landings: 2,521</p>
Engines	<p>Honeywell TFE731-60-1C</p> <p>SN: P112692 / P112693 / P112724</p> <p>4,940.4 / 4,940.4 / 4,957.7 Hours Since New</p> <p>Engines enrolled on MSP Gold</p>
APU	<p>Honeywell GTCP36-150F</p> <p>SN: P-508/3800188-2</p> <p>2,720 Hours Since New</p>
Avionics	<p>ADF: Dual Honeywell DF-855</p> <p>Autopilot: Honeywell Primus Epic IFCS</p> <p>Communication Radios: Triple Honeywell TR-866B w/8.33 Spacing</p> <p>Compass: Smith Standby</p> <p>CVR: Honeywell SSCVR</p> <p>DME: Dual Honeywell DM-855</p> <p>EFIS: Honeywell 4-tube</p> <p>FDR: Honeywell SSFDR</p> <p>Flight Director: Honeywell Primus Epic IFCS</p> <p>Flight Phone: Dual Thrane &amp; Thrane TT-5620A</p> <p>FMS: Triple Honeywell FMS</p> <p>GPS: Dual Honeywell GPS-90X</p> <p>Hi Frequency: Dual Collins HF-9000 w/Honeywell SELCAL</p> <p>IRS: Triple Honeywell LASEREF V</p> <p>Navigation Radios: Dual Honeywell NV-875A w/FM immunity</p> <p>Radar Altimeter: Dual Honeywell AA-300</p> <p>SATCOM: Aero H+ Swift 64 TT-5000</p> <p>Stormscope: Honeywell LSZ-860</p> <p>TAWS: Honeywell EGPWS</p> <p>TCAS: Honeywell TCAS-2000 w-change 7.1</p> <p>Transponder: Dual Honeywell XS-876 Mode S</p> <p>Weather Radar: Honeywell Primus 880</p>
Exterior	<p>Overall White with Black &amp; Grey Accent Stripes</p>



## Specs

### Highlights

Fresh 3C Inspection  
 ATG5000  
 HUD | Heads Up Display  
 EASy II Cert 4  
 FANS-1A | CPDLC  
 Push to Load Function  
 Enhanced Navigation  
 Triple Inertial Reference System  
 EVAS | Emergency Vision Assurance System  
 Third Flight Management System  
 Forward Crew Lav

### Interior

Refurbished in 2019: Woodwork; all leather seats; carpet; headliner and side walls.  
 Configuration: Executive 14 passengers  
 Refreshment: Forward full service 36-inch galley  
 Lavatory: Forward crew lav & aft lav  
 Seating: Single seats recovered in 2009 w/medium beige leather, forward double club seating w/four single executive seats, mid-cabin 4-place dining/conference group, dual aft 3-place 76-inch berthable divans  
 Headliner: Tapi Suede headliner  
 Carpet: Kalogridis Carrington Wave carpeting  
 Cabinetry/Wood: Satin finished Anigre wood veneer cabinetry, mid-cabin conference table, mid-cabin credenza  
 Entertainment: Airshow 410 cabin display system, Audio International MHGE entertainment/PA chime control module, MAP program interface module, entertainment control module & TCM temperature control module, Dual Audio International MHI infrared receiver modules & sensors, ten Audio International cabin speaker, two Audio International lav speakers, two membrane entertainment controls, ten Audio International entertainment controls, Twelve Sony MDR-V500 lightweight stereo headsets, Honeywell HB2000 20-inch LCD color monitor, Honeywell HB1500 15-inch LCD color monitor, six Rose O100-42 receptacles (5.6-inch/8.4-inch LCD), Auxiliary cabin audio/NTSC video interface, Audio International multi-region DVD/CD player, four Rosen 8.4-inch LCD color monitors, Audio International MHR infrared remote control  
 Accessories: Satin nickel plated hardware, aft lav satin nickel plated sink









## Trades Welcome.

Are you transitioning from another aircraft and need to sell that first?  
Enter information at [jetaviva.com/valuation](https://jetaviva.com/valuation) and we'll provide a trade-in credit.

