



2004 Hawker 800XP

SN 258653

Website jetaviva.com

Email sales@jetAVIVA.com

Phone +1.512.410.0295

Specs

Airframe	2004 Airframe 6,496 Hours 3,724 Landings 6,477 Hobbs
Recent Maintenance	B, C and D Inspections done October 2023 E Inspections done June 2025 F and G Inspections done September 2024 Engine #1 MPI done August 2023 Engine #2 MPI done August 2024 APU Hot Section Inspection done September 2023 Left Front Windscreen replaced October 2023 Right Front Windscreen replaced January 2025 Left Side Window replaced August 2021 Right Side Window replaced April 2020 Fuel tank leaks repaired October 2023
Engines	Honeywell TFE731-5BR (2) Engine 1: 6,493 hours / 3,719 cycles Engine 2: 6,496 hours / 3,724 cycles Engines enrolled on MSP Gold
APU	Honeywell GTCP 36-150W 4,579 Hours Enrolled on MSP Gold
Avionics	Collins Proline 21 with Synthetic Vision System upgrade Comm: Dual Collins VHF-422C Transceivers w/ 8.33 spacing Nav: Dual Collins FMS-6000 GPS: Dual Collins GPS-4000S Dual Collins IFIS-5000 Collins DBU-5010E HF: Dual HF-9000 with SELCAL Collins TCAS-II with change 7.1 Transponder: Dual Collins TDR-94D Collins RTA-858 Weather Radar Whelin Moon Beam taxi and landing lights EGPWS WAAS/LPV ADF XM Weather Briefing System
Exterior	New paint 2023 by Duncan Aviation with remainder of 3 year warranty
Interior	New interior 2020 3 place divan 9 pax with belted lav Wifi Airshow













Trades Welcome.

Are you transitioning from another aircraft and need to sell that first?
Enter information at jetaviva.com/valuation and we'll provide a trade-in credit.

